

Battery check-up

Date of diagnosis : 01/06/2023 at 15:02 Europe/Paris

Updated edition available on
<https://certificate.get-moba.com/certificates/1282ba91da.pdf>



Peugeot 3008 SUV 300 ch*

VIN : VF3M45GBUMS095483 IMMAT : FY-899-ES

Date of first registration : 29/03/2021

Mileage : 36,364 km

*As declared by the user at the time of diagnosis

Battery status



State of Health (SOH)*

State of Charge (SOC) measured during diagnosis

92%

Remaining capacity

12.00 kWh

We invite you to take a look at the warranty conditions for your battery: duration, mileage, number of cycles. As an indication, the average warranty observed in Europe for this vehicle is as follows: SOH greater than 70%, for 8 years or 160,000 km.

* SOH generated from vehicle-specific data and not tested independently of the vehicle.. Information to consider for the manufacturer's warranty.

Range*

☀ SUMMER (25°C)

☾ WINTER (0°C)

📍 Urban cycle :

63 - 69 km

48 - 53 km

📍 Motorway cycle :

43 - 47 km

36 - 40 km

📍 Combined cycle :

55 - 61 km

42 - 46 km

* In 100% electric mode



Learn more on :
www.get-moba.com

